

SIGNATURE				THANK YOU	2/10/20
-----------	--	--	--	-----------	---------

tr6 maintenance and history

From: **michael drebo** (mdrebo@hotmail.com)

Sent: Wed 5/09/12 12:00 PM

To: libertycall8107@hotmail.com

Michael Drebo
32819 Green Bend Ct
Magnolia, TX 77354
440-915-1472

doug,

the following is a synopsis of the maintenance history of the 1976 triumph tr6, vin cf50255u.

the automobile has 38,111 original miles.

engine compression test figures, from may 2012, #1 cylinder 115 psi, #2 cylinder 116 psi, #3 cylinder 118 psi, #4 cylinder 117 psi, #5 cylinder 116 psi, #6 cylinder 118 psi. the engine has never been overhauled.

i use castrol 20w-50. the engine oil and filter are changed every spring. fresh oil and filter march 2012, about 10 miles ago.

there was a small transmission leak in the forward seal. this past winter, november 2011, i removed the transmission, replaced the front seal, and installed a new clutch, pressure plate, throw-out bearing, starter, starter solenoid, and starter relay. i changed the gear box fluid and used lucas 80-90w.

the differential oil was changed in march 2012. i used lucas 80-90w.

the radiator coolant was changed november 2009. i used prestone anti-freeze at a 50/50 mixture with water. had i keep the vehicle, my next scheduled maintenace project (fall 2012) was to change all the coolant hoses and coolant. there is a complete green hose set, with new original style clamps, available through the roadster factory. i have included an old catalog.

about 5 years ago i went through the brake system. new front brake pads and rear brake shoes, new rear hydraulic cylinders, new brake master, new hydraulic reservoir, new brake booster, new rubber brake hoses and new hydraulic fluid. use only castrol hydraulic fluid in the hydraulic brake and hydraulic clutch systems. i have included 2 1/2 bottles in the parts box. i did not change the metal brake lines, as these were ok. all four wheel bearing sets were repacked. new front shocks were installed. this maintenance was about 500-700 miles ago.

NEW FRONT SHOCKS, ALL
NEW WHEEL BEARINGS

about three year ago i changed the clutch master, clutch slave and hydraulic hoses. once again, use only the castrol hydraulic fluid.

N/A about every other year i check and service the rear hydraulic shock absorbers. this is a pain to do, but is part of proper servicing. i have included a bottle of shock oil in the parts box.

as i stated over the phone, i purchase 5 gallons of avgas at the local airport and use a 50/50 mixture of avgas and service station fuel. a few service stations (maybe sunoco) have racing fuel available, that is an option.

the cars from the 1970's were designed to run on a higher octane, leaded fuel. i change the fuel filter about every five years. the current fuel filter is two years old.

all five tires are new cooker red lines.

when i put the top down, i place a cotton towel on top of the plastic window. i believe this reduces wear on the plastic window. i have place the boot cover, that i use behind the seats. the boot cover for modifying the tonneau cover is in the trunk with the tonneau cover.

if you have any further question don't hesitate.

for your planning with the shipping company, i have off may 22, 23, 24 and 25. i don't know how responsive they will be. if those dates don't work, i'll have my june schedule on may 17th and will forward my june days off.

michael

WORK INVOICE

VINTAGE RESTORATIONS, LTD

52 North Main Street, P.O. Box 573
Union Bridge, Maryland 21791-0573
(410) 775-0500

Name	Doug Randlett	Phone	757-270-6352 C	Date	8/12/13
Email	libertycall8107@hotmail.com		703-771-0923		
Street	327 Caldwell Ter. SE	City	Leesburg	State	VA 20175
Year	1976	Make	Triumph	Model	TR6
				Color	Green
				Inv. No.	320-01
Comm #	CF 50255 U	Mileage	40,440	Engine Number	

Work Description @ \$85/Hr.		Hours	Amount
1. Open hood; route cable above battery box; drill hole and install auxiliary hood release cable; remove wire that was previously installed		1.0	\$85.00
2. Check for fuel leaks, none found; check choke operation, no fast idle from choke lever; adjust screws to allow fast idle; choke lever only needs to be pulled out very minimally; test drive car, runs well.		0.5	\$42.50
3. Remove engine block drain plug to drain coolant; port is filled with debris, use wire to poke through hole; drain coolant, clean port with wire brush; flush water through cooling system to remove debris; start engine and get to operating temperature; remove drain plug and drain water and remaining dirt; back flush radiator; replace drain plug and add 50/50 mixture of coolant; warm engine and remove any air pockets; test drive car; no leaks, coolant temperature is good		1.0	\$85.00

COMMENTS:

Payment is due upon receipt of invoice.

Thanks, we appreciate your business!

Total Parts Amount	\$30.34
Parts Sales Tax @ 6%	\$1.82
Freight/Delivery/Insurance	\$0.00
Total Labor @ \$85/Hr.	\$212.50
Shop Charge (6% of Labor)	\$12.75
Subtotal	\$257.41
Credit	\$0.00
Amount Due	\$257.41



British & Classic Car Doctors
9183 John Mosby Highway
Upperville, VA 20184

Estimate

Date	Estimate #
6/18/2012	1038

Customer Phone

Name / Address
Doug Randlett 327 Caldwell terrace SE Leesburg, VA 20175

Mileage	Vin#	Project

Description	Qty	Rate	Total
Rear brakes are near the end of service life. Check rear brakes replace as needed. We where able to replace the rear wheel cylinders, but the shoes where defective and where unable to be installed	2.5	94.49	236.23
Wheel cylinder, classic gold aftermarket	2	15.95	31.90
Fitting kit, wheel cylinders	1	19.95	19.95
Retaining kit	1	15.95	15.95
Oil shocks, it needs to be done with the shocks off the vehicle. This will be done at another time. We have advised the customer that a tube shock conversion is the way to go, and cost about the same.	0	94.49	0.00
Brake Fluid flush	1	94.49	94.49
Brake fluid Castrol GT/LMA	3.5	5.00	17.50
hood cable has recently been replaced. Customer said it seems very tight wanted to see if it could be adjusted. We adjusted as we could but where limited as the latch mechanism needs to be completely gone thru and rebuilt.	0.25	94.49	23.62
Passenger side door gap seems off. Customer wanted to see if it could be adjusted. We where unable to do anything at this time with this.	0	94.49	0.00
There is a Bubble in one of the tires. Customer requested it be swapped with spare tire in trunk. Wants bad tire remove from the rim so he can send it in for warranty	0.25	94.49	23.62
shipping	1	14.62	14.62
Rags, Clean up time, and hardware	1	22.12	22.12
Total			\$500.00

540-592-3535
BRITISH & CLASSIC CAR D
9183 JOHN MOSBY HWY
UPPERVILLE VA 20184

Invoice

British & Classic Car Doctors
9183 John Mosby Highway
Upperville, VA 20184

Date	Invoice #
5/29/2012	779

Customer Phone

Phone #	540-945-5500
---------	--------------

ITEM #: 001

DATE: MAY 29, 2012 TIME: 11:46
AUTH NO: 005458

\$86.37

CUSTOMER COPY

P.O. Number	Terms	Rep	Ship	Mileage	Vin #	Project
			5/29/2012	38,190		

Quantity	Item Code	Description	Price Each	Amount
0.75	Labor Std. Service	Running issue. Replaced red rotor and vacuum elbow	94.49	70.87
1	Part	Red rotor	12.00	12.00
1	Part	Vacuum elbow - EGT	3.50	3.50
		reconfigured dist-ignition wiring.		

Total	\$86.37
Payments/Credits	\$-86.37
Balance Due	\$0.00

Round Hill Exxon
4 E Loudoun St
Round Hill, Va. 20141
Phone: 540-751-9665
WWW.ROUNDHILLEXXON.COM

INVOICE

13926

Org. Est. # 029199

INVOICE

Print Date:08/14/2015

RANDLETT, DOUG
15541 WHISPERING KNOLL CT
Purcellville, VA 20132
Mr. Cell : 757-270-6352
Cust ID : 2453

1976 Triumph - TR6 -

Lic # : -

Odometer In : 0

Odometer Out : 43630

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Extended
WHEEL WEIGHTS	4.00	1.50	6.00	4 X COMPUTER SPIN BALANCE	0.62	48.00
WGTS01				ALL WHEELS SLIGHTLY BENT AND ALL TIRES SLIGHTLY OUT		
Shop Supplies			2.88	OF ROUND		
				Hazardous Materials/Disposal		0.96

[Payments -]

Sign up for our E-Mail Specials at www.roundhillexxon.com

I hereby authorize the above repair work to be done along with the necessary materials and hereby grant you and your employees permission to operate the vehicle for the purpose of testing and / or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Warranty work on labor is 12 months / 12,000 miles. All other warranties (parts) are made by the manufacturer. All warranty work must be performed at this location. Returned checks subject to \$50 fee and electronic debit.

Labor:	48.96
Parts:	8.88
Sub:	57.84
Tax:	0.53
Total:	\$58.37
Bal Due:	\$58.37

Sign up for our E-Mail Specials at www.roundhillexxon.com

Signature _____ Date _____ Time _____

Round Hill Exxon

4 E Loudoun St

Round Hill, Va. 20141

Phone: 540-751-9665 Fax: 540- -

WWW.ROUNDHILLEXXON.COM

INVOICE**36040**

Org. Est. # 052863

INVOICE

Work Completed : 02/14/2019

Date: 02/14/2019

RANDLETT, DOUG

15541 WHISPERING KNOLL CT

Purcellville, VA 20132

Mr. Work 703-275-2620 -- Mr. Cell 757-270-6352

1976 Triumph - TR6 -

Lic # :

Odometer In : 0

Odometer Out : 45948

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
OIL FILTER	1.00	27.74	27.74	INSTALL ORIGINAL OIL FILTER		
FILTER				INSTALL STOCK FILTER HOUSING	0.50	44.75
Shop Supplies			2.69	Hazardous Materials/Disposal		0.90

[Payments -]

Sign up for our E-Mail Specials at www.roundhillexxon.com

I hereby authorize the above repair work to be done along with the necessary materials and hereby grant you and your employees permission to operate the vehicle for the purpose of testing and / or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Warranty work on labor is 12 months / 12,000 miles. All other warranties (parts) are made by the manufacturer. All warranty work must be performed at this location. Returned checks subject to \$50 fee and electronic debit.

Labor:	44.75
Parts:	30.43
HazMat:	0.90
Sub:	76.08
Tax:	1.83
Total:	\$77.91
Bal Due:	\$77.91

Sign up for our E-Mail Specials at www.roundhillexxon.com

Vehicle Received: 2/14/2019

Customer Number : 2453

Signature _____

Date _____

Our Email Address: **INFO@ROUNDHILLEXXON.COM**

U K MOTORSPORTS LLC

810 ST. CHRISTOPHERS RD
RICHMOND, VA 23226

Invoice

Date	Invoice #
4/12/2013	248

Bill To
Doug Randlett 327 Caldwell Ter SE Leesburg, VA 20175-5689

Make	Model	Mileage	VIN
1976 Triumph	TR6	39,789	CF50255U

Item	Description	Qty	Rate	Amount
Labor	courtesy inspection (NO CHARGE)	2	0.00	0.00
Labor	install rear tube shock conversion, modify support w/ additional bracing	2.5	85.00	212.50
Labor	remove exhaust rear section and muffler, replace intermediate pipes, exhaust mount kit, remove broken pipes from rear muffler clean and install	2.5	85.00	212.50
Labor	remove differential, replace pinion seal, side stub axle seals	5	85.00	425.00
Labor	clean, prep, and weld right front differential mount bracket assembly	2	85.00	170.00
Labor	replace differential front and rear rubber mounts(NO CHARGE)	2	0.00	0.00
Labor	remove left and right rear splined axle assemblies, replace (4) u-joint assemblies, clean and grease axle splines and replace spline gator	4	85.00	340.00
Labor	inspect front and rear brake assemblies(NO CHARGE)	1	0.00	0.00
Labor	perform front brake Toyota caliper conversion, replace rotors, replace front brake pads	4	85.00	340.00
Labor	replace front and rear brake hoses with uprated braided stainless steel	3	85.00	255.00

	Subtotal
Pay online at: https://ipn.intuit.com/tx2hfxgb	Sales Tax (5.0%)
	Total
	Payments/Credits
	Balance Due

Phone #

U K MOTORSPORTS LLC

810 ST. CHRISTOPHERS RD
RICHMOND, VA 23226

Invoice

Date	Invoice #
4/12/2013	248

Bill To
Doug Randlett 327 Caldwell Ter SE Leesburg, VA 20175-5689

Make	Model	Mileage	VIN
1976 Triumph	TR6	39,789	CF50255U

Item	Description	Qty	Rate	Amount
Labor	bleed brake system, bed in front brakes (NO CHARGE)	1	0.00	0.00
Labor	remove carburetors for rebuilding	1	85.00	85.00
Labor	install carbs, and bead blasted intake manifold	2	85.00	170.00
Labor	remove distributor for rebuilding	0.5	85.00	42.50
Labor	install rebuilt distributor, set timing, adjust carburetor mixture, idle	1.5	85.00	127.50
Labor	replace accelerator shaft bushings	1.5	85.00	127.50
Labor	replace front sway bar links	1	85.00	85.00
Labor	secure convertible top handles(NO CHARGE)	1	0.00	0.00
Labor	inspect and set front wheel bearing runout(NO CHARGE)	1	0.00	0.00
Labor	replace water pump	2	85.00	170.00
Labor	replace all engine bay cooling system hoses	3	85.00	255.00
Labor	replace heater control cable assembly	1	85.00	85.00
Labor	replace heater box vent control cable assembly	1	85.00	85.00
Labor	adjust valves	1	85.00	85.00
Labor	change oil and filter, lube front suspension	0.5	85.00	42.50
Labor	change transmission gear oil (Redline MTL)	0.5	85.00	42.50
Labor	fill differential assembly(NO CHARGE) Valvoline Synthetic	0.5	0.00	0.00

Subtotal

Sales Tax (5.0%)

Total

Payments/Credits

Balance Due

Pay online at: <https://ipn.intuit.com/tx2hfxgb>

Phone #

U K MOTORSPORTS LLC

810 ST. CHRISTOPHERS RD
RICHMOND, VA 23226

Invoice

Date	Invoice #
4/12/2013	248

Bill To
Doug Randlett 327 Caldwell Ter SE Leesburg, VA 20175-5689

Make	Model	Mileage	VIN
1976 Triumph	TR6	39,789	CF50255U

Item	Description	Qty	Rate	Amount
Labor	replace temp gauge with proper refurbished/calibrated unit	0.75	85.00	63.75
Labor	replace inop dash light bulbs(NO CHARGE)	1	0.00	0.00
Labor	repaire under dash lighting(NO CHARGE)	1	0.00	0.00
Labor	adjust drivers door striker(NO CHARGE)	0.5	0.00	0.00
Labor	inspect convertible top operation(NO CHARGE)	0.5	0.00	0.00
Labor	remove air pump, belt, injection manifold, gulp valve,etc, related smog items	1	85.00	85.00
Labor	replace alternator/wp belt (NO CHARGE)	1	0.00	0.00
Labor	bead blast and paint intake manifold (NO CHARGE)	1	0.00	0.00
Sublet Labor	distributor rebuilding services	1	155.00	155.00
Sublet Labor	carburetor rebuilding services	1	500.00	500.00
Sublet Labor	gauge refurbishment service	1	87.00	87.00
Used Part	used temp gauge	1	25.00	25.00

Subtotal

Sales Tax (5.0%)

Total

Payments/Credits

Balance Due

Pay online at: <https://ipn.intuit.com/tx2hfxgb>

Phone #

U K MOTORSPORTS LLC

810 ST. CHRISTOPHERS RD
RICHMOND, VA 23226

Invoice

Date	Invoice #
4/12/2013	248

Bill To
Doug Randlett 327 Caldwell Ter SE Leesburg, VA 20175-5689

Make	Model	Mileage	VIN
1976 Triumph	TR6	39,789	CF50255U

Item	Description	Qty	Rate	Amount
Parts	tube shock conversion kit	1	221.81	221.81T
Parts	exhaust section	2	35.00	70.00T
Parts	install kit	1	73.00	73.00T
Parts	pinion seal	1	7.00	7.00T
Parts	stub axle seal	2	4.00	8.00T
Parts	diff mount reinforcements	2	15.00	30.00T
Parts	u-joint	4	28.00	112.00T
Parts	gator	2	10.00	20.00T
Parts	front rotor	2	75.00	150.00T
Parts	Toyota caliper	2	100.00	200.00T
Parts	premium front metalmaster pads	1	95.00	95.00T
Parts	braided brake lines	1	135.00	135.00T
Parts	differential mount kit	1	60.00	60.00T
Parts	accelerator shaft bushing	2	6.00	12.00T
Parts	front sway bar links	2	20.00	40.00T
Parts	water pump	1	78.00	78.00T
Parts	cooling system hose kit	1	60.00	60.00T
Parts	heater control cable	1	43.00	43.00T
Parts	vent control cable	1	43.00	43.00T
Parts	oil filter	1	6.00	6.00T

Subtotal

Sales Tax (5.0%)

Total

Payments/Credits

Balance Due

Pay online at: <https://ipn.intuit.com/tx2hfxgb>

Phone #

U K MOTORSPORTS LLC
810 ST. CHRISTOPHERS RD
RICHMOND, VA 23226

Invoice

Date	Invoice #
4/12/2013	248

Bill To
Doug Randlett 327 Caldwell Ter SE Leesburg, VA 20175-5689

Make	Model	Mileage	VIN
1976 Triumph	TR6	39,789	CF50255U

Item	Description	Qty	Rate	Amount
Parts	Brad Penn 20w50	6	6.75	40.50T
Parts	Redline MTL	3	18.00	54.00T
Parts	Valvoline Synthetic gear oil	3	10.00	30.00T
Parts	dash bulb	2	2.95	5.90T
Parts	dash bulb	1	2.95	2.95T
Parts	alternator belt	1	11.00	11.00T
Parts	intake stud	8	1.95	15.60T
Parts	washer	8	0.15	1.20T
Parts	brass nut	8	0.95	7.60T

Subtotal \$5,905.81

Sales Tax (5.0%) \$81.63

Total \$5,987.44

Payments/Credits \$0.00

Balance Due \$5,987.44

Pay online at: <https://ipn.intuit.com/tx2hfxgb>

Phone #

U K MOTORSPORTS LLC

810 ST. CHRISTOPHERS RD
RICHMOND, VA 23226

Invoice

Date	Invoice #
4/22/2015	324

Bill To
Doug Randlett 327 Caldwell Tos SE Leesburg, VA 20175-5689 <i>Sent Chip new address</i>

Make	Model	Mileage	VIN
Triumph	TR6	39,780 43,050	

Item	Description	Qty	Rate	Amount
Labor	perform courtesy inspection (NO CHARGE)	2	0.00	0.00
Labor	slight whirring noise from clutch/transmission...most likely input shaft turning when motor is running at idle...noise is not present when clutch is depressed...if noise gets worse then transmission may need attention (NO CHARGE)	0.5	0.00	0.00
Labor	turn signals slow and unresponsive...diagnose and replace signal flasher unit	0.5	85.00	42.50
Labor	check/replace rear brakes...checked and adjusted rear brakes...plenty of shoe material	0.5	85.00	42.50
Labor	right front tire wore quickly on outside edge...performed 4-wheel alignment...toe in was excessive with the front tires, adjusted rear toe, checked front camber, caster and rear camber	2	85.00	170.00
Labor	blue smoke on over run...not a concern at this time...plugs are not fouling and look good (NO CHARGE)	0.5	0.00	0.00
Labor	rocker arms adjustment...remove and inspect rocker shaft assembly...OK at this time...adjust valves...replace valve cover gasket with silicone type	2	85.00	170.00
Labor	change oil and filter	0.5	85.00	42.50
Labor	check all fluids	0.5	85.00	42.50

Subtotal

Sales Tax (5.3%)

Total

Payments/Credits

Balance Due

Phone #

U K MOTORSPORTS LLC

810 ST. CHRISTOPHERS RD
RICHMOND, VA 23226

Invoice

Date	Invoice #
4/22/2015	324

Bill To
Doug Randlett 327 Caldwell Ter SE Leesburg, VA 20175-5689

Make	Model	Mileage	VIN
Triumph	TR6	39,789	

Item	Description	Qty	Rate	Amount
Labor	RR light needs bulb...replace side marker bulb	0.1	85.00	8.50
Labor	rattle on rt side on bumps...noted wheel trim rings and valve stem covers may be making noise, also possible front brake pad rattle...nothing loose and dangerous (NO CHARGE)	0.5	0.00	0.00
Labor	installed bullet mirror on passenger door, re-secure drivers side mirror assembly	1	85.00	85.00
Labor	removed trunk contents and trim panel...loosen and reposition fuel cap	0.8	85.00	68.00
Labor	remove radiator shroud, grill assembly ...replace grill finisher	2	85.00	170.00
Labor	inspect and adjust front wheel bearings	1	85.00	85.00
Labor	adjust wiper arm assemblies positioning to better fit windshield (NO CHARGE)	0.5	0.00	0.00
Labor	replace broken anti-run-on valve with used unit	0.5	85.00	42.50
Parts	signal flasher relay	1	14.00	14.00T
Parts	oil filter element	1	4.00	4.00T
Parts	grill finisher	1	43.00	43.00T
Parts	silicone valve cover gasket	1	25.00	25.00T

Subtotal

Sales Tax (5.3%)

Total

Payments/Credits

Balance Due

Phone #

U K MOTORSPORTS LLC

810 ST. CHRISTOPHERS RD
RICHMOND, VA 23226

Invoice

Date	Invoice #
4/22/2015	324

Bill To
Doug Randlett 327 Caldwell Ter SE Leesburg, VA 20175-5689

Make	Model	Mileage	VIN
Triumph	TR6	39,789	

Item	Description	Qty	Rate	Amount
Parts	door mirror	1	45.00	45.00T
Parts	bulb	1	3.00	3.00T
Parts	Brad Penn 20w/50	6	6.00	36.00T
Used Part	anti-run-on valve	1	38.00	38.00
Parts	RTV red high temp	1	6.00	6.00T
			Subtotal	\$1,183.00
			Sales Tax (5.3%)	\$9.33
			Total	\$1,192.33
			Payments/Credits	\$0.00
			Balance Due	\$1,192.33

Phone #

Paid \$1,250.00

Termin
345319173

QTY.	PART NO. AND DESCRIPTION	PRICE
1	Clutch Master Cylinder	90 00
1	Clutch Slave Cylinder	80 00
3pc	Clutch Set	270 00
1	Front Frame Seal	6 00
1	Rear engine Seal	17 00
1	Rear Frame Seal	6 00
1	pilot Bush	6 00
1	Rear gear oil	2 00
1	Front gear oil	2 00
1	Clutch Fork	65 00
1	Clutch Shaft	45 00

\$1000.00

Thanks Doug,
Jeff

Note: Diff pinion Seal not installed
Shift noise may be gearbox

(MAY BE CONTINUED ON OTHER SIDE)	
TOTAL PARTS	529 00
ACCESSORIES	
* First Motion Shaft bearing Exhaust Mount changed done w/ diff gear work Exhaust mounting is solid & than	
In event of default of payment customer agrees to pay all collection and attorney fees.	
TOTAL ACCESSORIES	

Total 2996.50
- Diff \$1000.00
*1996.50 Balance

MOTORHEAD, LTD.
2811-B Old Lee Highway
Fairfax, Virginia 22031
(703) 573-3140 - Parts

20966

NAME Doug Randall	CUSTOMER'S ORDER NO. Jeff	DATE 10/5/12
ADDRESS	ORDER WRITTEN BY	PROMISED
CITY, STATE, ZIP		A.M. P.M.
HOME PHONE	BUS. PHONE 757 270 6352	EXT.
YEAR, MAKE AND MODEL 76 TR6	LICENSE NUMBER	ODOMETER IN
SERIAL NUMBER	MOTOR NUMBER	ODOMETER OUT
TERMS		Bill

DESCRIPTION OF WORK	AMOUNT
<input type="checkbox"/> LUBE <input type="checkbox"/> CHANGE OIL <input type="checkbox"/> OIL FILTER <input type="checkbox"/> TUNE-UP <input type="checkbox"/> TRANS. <input type="checkbox"/> DIFF.	
Check Clutch R+R, Rear engine Seal R+R Clutch Master Cylinder, Slave Clutch + Bleed Clutch R+R Inlet Clutch R+R rear engine Seal R+R F+R gear oil Seal R+R Shaft + fork R+R pilot bush Modify gear oil Seal 1 lighter Bonnet Latch Test Drive Check for proper Check diff pinion Seal Top up differential, gearbox, under bonnet	
_____ LITERS/GALS. OF GAS @	TOTAL LABOR 2315 00
_____ LITERS/QTS. OF OIL @ gear oil 12	TOTAL PARTS 529 00
_____ kg/LBS. OF GREASE @	ACCESSORIES
LMA 9.00	GAS, OIL AND GREASE 21 00
Machine Flywheel	SUBLET REPAIRS 65 00
Shaylee	EPA / WASTE DISPOSAL 14 50
	TAX 24 50
	TOTAL 2996 50
THANK YOU	

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

SAVE OLD PARTS? ☐ YES ☐ NO

SIGNATURE