



MENU

 (888) 231-7965

REPORT #665863


1981 MERCEDES-BENZ SL 450

[Click to View Large Gallery](#)



[Download Full-size Pictures \(zip\)](#)

Videos



0729.mp4

[Download \(mp4\)](#)

SUMMARY

Tires

The front and rear tires are in good condition and have been installed about 6 years ago per the tires DOT numbers. The front tires have light use with a 7/32nds tread depth on the front wheels, and the rear tires are at a 8/32nds as well. Refer to the pictures for the tread depth measurements.

Exterior

The initial appearance of this vehicle looks great. All the body panels looked straight, the overall paint condition was in good condition. The driver and passenger side skirts are free of any damages. All of the exterior trim decals were all in the correct orientation. The front and rear bumpers are in great condition and aren't showing any signs of pitting chrome. The rear stereo antenna for the vehicle seems to be broken or missing, and you'll see that there is a small blemish/dent right above that section, see picture.

Interior

The interior section of this vehicle is just in great condition. There are no burns in the floorboards or on any of the seats. All the door panels are in great condition without any signs of abuse or damaged components. The overall cleanliness of the interior floorboards is perfect. All the electrical interior components have been tested to ensure top tier condition. Now for the power windows, they all function but they go up rather slowly and I feel they will need to be replaced with newer parts to ensure proper speed when going up or down. The overall interior of this vehicle looks really great. This vehicle also comes with a removable hard top that hides a complete soft top section.



















Mechanical


























The engine bay compartment has been well maintained, all of the belts are in good working order and free of cracks or signs of concerns. All of the fluids are at the right capacity (Engine Oil, Brake Fluid) The electrical system was operating at default factory standards. And the only issue for the engine compartment is it can use a little detail to make engine section look cleaner and remove surface dirt. But the vehicle starts up and idles exactly how it should.

Road Test

















Unable to perform test drive as the tires are observed to be over 6 years old and should be replaced due to their age for preventive maintenance.



VEHICLE INFO	
YEAR	1981
MAKE	Mercedes-Benz
MODEL	SL 450
MILEAGE	88727
TRANSMISSION	Automatic
VIN NUMBER	WDB10704412062673
INTERIOR	Leather
INTERIOR COLOR	Tan
BODY COLOR	Red
ENGINE	8 Cylinder
DRIVE TYPE	Front Wheel Drive
FUEL TYPE	Gas

EXTERIOR	
WIPER BLADES	
WINDSHIELD WASHER	
BODY ALIGNMENT	
SCRATCHES	
There are minor misc scratches around the vehicle. Normal for mileage and most too small to see in photos.	
PAINT CONDITION	
EXTERIOR LIGHTS	
DOOR MIRRORS	
BUMPERS	
SIDE MOLDINGS	
CONVERTIBLE TOP	
GLASS	
BODY SEALS	
HOOD	
DOORS	
FLOORS	
ROCKERS	
QUARTER PANELS	
CHROME	

INTERIOR	
STEERING WHEEL	
HORN	
CRUISE CONTROL	
It wasn't tested due to the current tire conditions.	
SEAT CONDITION	
There is light wear to the seats.	
SEAT BELTS	
CLOCK	
RADIO/NAVIGATION	
INNER DOOR PANELS	
POWER LOCKS	
WINDOW SWITCHES	
WINDOW FUNCTION	
CENTER CONSOLE	
DASH	
SUN VISORS	
DASH LIGHTS	
DASH GAUGES	
AIR CONDITIONING	
HEATER	
CARPET	
FLOOR MATS	
CUP HOLDERS	
HEADLINER	
BLOWER MOTOR	
INTERIOR TRIM	
INNER TRUNK	

CONDITION

MECHANICAL	
AIR FILTER	
BATTERY CONDITION	
CHARGING SYSTEM	
COOLING FAN CONDITION	
RADIATOR CAP SEALING PROPERLY	
HOSES	
RADIATOR	
ENGINE COOLANT	
BELTS	
POWER STEERING	
ENGINE OIL	
BRAKE SYSTEM	
MUFFLER SYSTEM	
CV JOINTS AND AXLES	
SHOCKS AND BUSHINGS	
BALL JOINTS AND TIE RODS	

ROAD TEST	
ROAD TEST Unable to perform test drive as the tires are observed to be over 6 years old and should be replaced due to their age for preventive maintenance.	
ENGINE PERFORMANCE	
ENGINE STARTING	

MANUFACTURER

Driver Front	Sailun	Sailun	Passenger Front
Driver Rear	Sailun	Sailun	Passenger Rear

SIZE

Driver Front	205/70R14	205/70R14	Passenger Front
Driver Rear	205/70R14	205/70R14	Passenger Rear

AXLE COUNT

Driver Front	1	1	Passenger Front
Driver Rear	1	1	Passenger Rear

TIRE CONDITION

Driver Front	No Issues	No Issues	Passenger Front
Driver Rear	No Issues	No Issues	Passenger Rear

WHEEL CONDITION

Driver Front	No Issues	No Issues	Passenger Front
Driver Rear	No Issues	No Issues	Passenger Rear

TIRE TREAD

Driver Front	7/32	7/32	Passenger Front
Driver Rear	8/32	8/32	Passenger Rear

SPARE TIRE

SPARE TIRE	Yes
-------------------	-----

TIRE TREAD EXPLANATION





10/32 OR MORE

Tires have plenty of tread!
(standard)

8/32 OR MORE

Tires have plenty of tread!
(low profile)

5/32 TO 7/32

Tires will need replacement soon!

4/32 OR LESS

Tires need replacement!



THE BEST WAY TO BUY TIRES

Say hello to discounts and enjoy the best rates on your new tires.

SHOP TIRES



DON'T SPEND YOUR HARD EARNED MONEY ON A LEMON. GET YOUR VEHICLE INSPECTED

ORDER NOW



Contact

Phone: (888) 231-7965

Orders may be placed online 24/7

SOCIAL FEEDS



BECOME AN INSPECTOR

2024 © ALL Rights Reserved. Privacy Policy | Terms of Service.